

ORGNAISATIONAL CONTEXT



Organisational Scope Statement



VERSION NO.	DATE (M/Y)	DESCRIPTION	WRITTEN BY	APPROVED BY
1	Aug 2019	New Document	Dale Earnshaw - Consultant	Senior Management MR Review
2	July 2021	Changed the format of the document. No other changes were required.	Dale Earnshaw - BMSQ MANAGER	Senior Management MR Review

This statement has been considered using the process for analysing our organisational context, which comprises internal and external issues and the requirements of interested parties.

The scope states the types of products and services covered by our quality management system, along with justification for any operational requirement from Section 8 of ISO 9001:2015 that cannot be applied.

PRIORITY POWDER COATING'S ORGANISATIONAL SCOPE STATEMENT

"Our organisation provides a decorative and protective powder coating service, as well as an abrasive blasting service, to customer supplied metal products, for the domestic, recreational, architectural, commercial & industrial sectors. We are Dulux and AkzoNobel Accredited Powder Coaters and we use a high quality, supplier provided powder coat that ensures a long lasting, exceptional finish.

Our head office, located at 13 Reliance Drive Tuggerah, NSW, 2259, houses our high volume, powder coating and abrasive blasting facilities and our administrative support and customer service divisions. Our second site, located at 4A Burnet Road, Warnervale NSW 2259, operates as a small pre-treatment, powder coating and curing facility.

Our organisation uses a custom-built job tracking and a production scheduling software programme, which ensures we operate within the ISO 9001:2015 standard guidelines.

We exclude ISO 9001:2015- 8.3 design and development from our Quality Management System, as we do not design or modify components"

This document is also published in Priority Powder Coatings Quality Manual and our TIP Website: https://tip.prioritypowdercoating.com/ on the Home Page.

Doc No. QMS-102-Po Approval Date: 22/07/2021 Approver Title: Business Systems Director Not a controlled document when printed